Approved For Rele	ease 2002/11/15 :	CIA-RDP89B	00980R0	003000400	26-0	
Lockheed Aircraft Corp.		NEERING STUDY		A. C - 57-1		
DATE 11-18-59 AFFE		: ws	PO 10	PF	OJECT	X
NAME OF MAJOR COMPONENT Shipts Wiring	PART OR LOWES Electrical F (Engine Co	larness		PART NO.	& MODEL	OR TYPE
TITLE OF PROPOSAL : Replac	ement Wiring -		artment	;		
NATURE OF PROPOSAL:		· · · · · · · · · · · · · · · · · · ·				
1. Replace wiring harness with high temperature	run L.H. side wire MIL-C-250	fuselage be 38 or ROCKBE	tween F STOS 67	S 319 and B.	FS 555,	· · · › - · - · · · ·
2. Prepare and issue Serv	ice Bulletin h	28.		. £		Ì
3. Fabricate kits for S.E	. 428 for all	Articles.		٠		
4. Kits to be installed on IRAN.						
NOTE: Revised to Avoi	d Necessity of	Splicing at	FS 1419			
REASON FOR PROPOSAL:		. .				
1. This is item C, para. **FOG IRAN Program* dat	9 of the list ed Aug. 1959	of improveme	nt item	s include	d in	
2. Past history indicates insulation in the engi	that engine h	eat is causi	ng dete	rioration	of wire	
NOTE: This ECP would stan Some ships had the other ships have had (See ECP LAC-33).	intent of this	ECP perform	ed at L	aughlin Al	TR and	
ESTIMATED COST AND TIME	INVOLVED :					
ES ADDITIONAL FUNDING REQU	IRED :	•				
CP ESTIMATED COST FOR KITS C			t (as r	equired)		
ITEMS AFFECTED BY PROPOSAL :					····	
SAFETY MISSION PERFORM OPERATE PROCEED	URE CHANGE WEIG	GHT OR TOOLS & SUPPORT ANCE EQUIPMENT	MAINTE- NANCE PROCEDUR	LIFE	FLIGHT MANUAL	MAINTE- NANCE MANUAL
				5		
EST. MAN/HRS. REQ'D. TO ACCOMP	LISH CHANGE IN	FIELD				
SOURCE OF PARTS FOR KIT 7		AVAILABILITY BETTAXABET, APPRIMENT				
LAC		To Meet	IRAN So	hedule		
DISPOSITION OF SPARES AFFECTED None						
INITIATED BY :		APPROVED: WSPSEIGHT				
LAC		12/3/0	PROJEC	:T]		\$7
Approved For Rel	ease 2002/11/15 : ·	CIA-RDP89B	90980R0	00 3000400		J